



Wilfrid Laurier University - 2023 Asbestos Management Database

Building:	Figures:	Notes:
<b>6 - Dining Hall</b>		<b>HM</b> - Homogenous Material - Homogeneous with previously sampled material
<b>Date Built:</b>		<b>SL</b> - Sample Location - Material Sampled
<b>1962</b>		<b>VC</b> - Visually Confirmed - Deemed ACM based on surveyor recognition
<b>Building Size:</b>		<b>AMP</b> - Asbestos Management Plan
<b>3035 m<sup>2</sup></b>		<b>ACM</b> - Asbestos-Containing Material

Room No.	Wing	Room Name	Access	Inspected Item	Inspected Material	Material Composition	Material Description	Material Detailed Location	Friability	Approximate Quantity	Unit(s)	Condition	Photograph	Sample / Identification Summary	Sample Name	% Asbestos & Fibre Type	Substrate Classification	Laboratory Report	Recommended Action	Recommended Abatement Operation	Whole Building Documentation	General Notes
DH101		Storage	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Short Random Fibrous	Ceiling									Non-ACM				No	Area Renovated
DH101		Storage	Yes	Wall	Ceramic Tile	Ceramic	Grey	Wall									Non-ACM				No	
DH101		Storage	Yes	Ducting	Ducting Insulation	Non Insulated	Unfinished	Above False Ceiling									Non-ACM				No	
DH101		Storage	Yes	Structural	Firespray	Cementitious	Grey	Steel Deck & C.W.S.L.						SL	32774-120-501abc	ND	Non-ACM		See Abatement Report		No	32774-120
DH101		Storage	Yes	Piping	Pipe Insulation	Fiberglass	Strapless and	Ceiling									Non-ACM				No	
DH101		Storage	Yes	Floor	Terrazzo	Terrazzo	Grey	Floor									Non-ACM				No	
DH101A		Freezer	Yes	Wall	Metal	Metal	White	Wall									Non-ACM				No	
DH101A		Freezer	Yes	Ceiling	Metal	Metal	White	Wall									Non-ACM				No	
DH101A		Freezer	Yes	Structural	Not Visible			Above False Ceiling									Suspect ACM				No	
DH101B		Freezer	Yes	Floor	Terrazzo	Grey	Floor										Non-ACM				No	
DH101B		Freezer	Yes	Wall	Metal	Metal	White	Wall									Non-ACM				No	
DH101B		Freezer	Yes	Wall	Metal	Metal	White	Wall									Non-ACM				No	
DH101B		Freezer	Yes	Ceiling	Metal	Metal	White	Wall									Non-ACM				No	
DH101B		Freezer	Yes	Structural	Not Visible			Above False Ceiling									Suspect ACM				No	
DH101B		Freezer	Yes	Floor	Terrazzo	Grey	Floor										Non-ACM				No	
DH101C		Freezer	Yes	Floor	Metal	Metal	Unfinished	Floor									Non-ACM				No	
DH101C		Freezer	Yes	Wall	Metal	Metal	White	Wall									Non-ACM				No	
DH101C		Freezer	Yes	Ceiling	Metal	Metal	White	Wall									Non-ACM				No	
DH101C		Freezer	Yes	Structural	Not Visible			Above False Ceiling									Suspect ACM				No	
DH101D		Freezer	Yes	Wall	Metal	Metal	White	Wall									Non-ACM				No	
DH101D		Freezer	Yes	Ceiling	Metal	Metal	White	Wall									Non-ACM				No	
DH101D		Freezer	Yes	Structural	Not Visible			Above False Ceiling									Suspect ACM				No	
DH101D		Freezer	Yes	Floor	Terrazzo	Grey	Floor										Non-ACM				No	
DH102		Mechanical Room	Yes	Floor	Concrete	Concrete	Grey	Floor									Non-ACM				No	
DH102		Mechanical Room	Yes	Wall	Concrete Block	Concrete	Grey	Wall									Non-ACM				No	
DH102		Mechanical Room	Yes	Ducting	Ducting Insulation	Non Insulated	Unfinished	Below Structure									Non-ACM				No	
DH102		Mechanical Room	Yes	Structural	Firespray	Cementitious	Grey	Steel Deck & C.W.S.L.						HM	DH 0H1-03-F5-54-001,0,N	ND	Non-ACM		07-225L		No	
DH102		Mechanical Room	Yes	Wall	Over Spray	Cementitious	Grey	Wall						HM	DH 0H1-03-F5-54-001,0,N	ND	Non-ACM		07-225L		No	
DH102		Mechanical Room	Yes	Piping	Pipe Insulation	Non Insulated	Unfinished	Below Structure									Non-ACM				No	
DH102		Mechanical Room	Yes	Piping	Pipe Insulation	Rubber	Black	Below Structure									Non-ACM				No	
DH103		Loading Dock	Yes	Wall	Brick	Brick	Beige	Wall									Non-ACM				No	
DH103		Loading Dock	Yes	Wall	Concrete	Concrete	Grey	Wall									Non-ACM				No	
DH103		Loading Dock	Yes	Wall	Concrete Block Painted	Concrete	Beige	Wall									Non-ACM				No	
DH103		Loading Dock	Yes	Wall	Drywall	Drywall Joint Compound	Beige	Wall									Non-ACM				No	
DH103		Loading Dock	Yes	Ceiling	Drywall	Drywall Joint Compound	Beige	Ceiling						HM	103316-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH103		Loading Dock	Yes	Ducting	Ducting Insulation	Fiberglass	White	Below Structure									Non-ACM				No	
DH103		Loading Dock	Yes	Ducting	Ducting Insulation	Non Insulated	Unfinished	Below Structure									Non-ACM				No	
DH104		Loading Dock	Yes	Structural	Firespray	Cementitious	Grey	Steel Deck & C.W.S.L.						SL	DH 0H1-03-F5-54-001,0,N	ND	Non-ACM		07-225L		No	
DH104		Storage	Yes	No Access													Suspect ACM				No	
DH107		Storage	Yes	Wall	Brick	Brick	Beige	Wall									Non-ACM				No	
DH107		Storage	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Short Random Fibrous	Ceiling									Non-ACM				No	Area Renovated
DH107		Storage	Yes	Floor	Concrete	Concrete	Grey	Floor									Non-ACM				No	
DH107		Storage	Yes	Wall	Concrete Block Painted	Concrete	Beige	Wall									Non-ACM				No	
DH107		Storage	Yes	Ceiling	Drywall	Drywall Joint Compound	Beige	Above False Ceiling						HM	103316-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH107		Storage	Yes	Wall	Drywall	Drywall Joint Compound	Beige	Wall									Non-ACM				No	
DH107		Storage	Yes	Ducting	Ducting Insulation	Non Insulated	Unfinished	Below Structure						SL	32774-DH&PM-501a	ND	Non-ACM		Sampled during 2010 for AMP		No	Sampled during 2010 for 2011 Update
DH107		Storage	Yes	Structural	Firespray	Cementitious	Grey	Steel Deck & C.W.S.L.						HM	DH 0H1-03-F5-54-001,0,N	ND	Non-ACM		07-225L		No	
DH108		Kitchen	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Short Random Fibrous	Ceiling									Non-ACM				No	Area Renovated
DH108		Kitchen	Yes	Wall	Ceramic Tile	Ceramic	Grey	Wall									Non-ACM				No	
DH108		Kitchen	Yes	Wall	Drywall	Drywall Joint Compound	Beige	Wall						HM	1033216-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	New Flooring
DH108		Kitchen	Yes	Floor	Roll'd Vinyl Flooring	Vinyl	Grey	Floor	Non-Friable	2000	Sq. Ft.	Good					Non-ACM				No	Area Renovated
DH108		Kitchen/Service	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small Fibrous & random	Ceiling						HM	1033216-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	Area Renovated
DH108		Kitchen/Service	Yes	Walls	Drywall	Drywall Joint Compound	Yellow	Walls						HM	1033216-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH108		Kitchen/Service	Yes	Structural	Firespray	Cementitious	Grey	Above False Ceiling						HM	32774-6-DH111-501abc	ND	Non-ACM		Misc. Blags		No	
DH108		Kitchen/Service	Yes	Piping	Pipe Insulation	Fiberglass Strapless and	White	Above False Ceiling									Non-ACM				No	
DH108		Kitchen/Service	Yes	Floor	Roll'd Vinyl Flooring	Vinyl	Dark/Brown with Red Fle	Floor									Non-ACM				No	
DH108		Kitchen/Service	Yes	Ducting	Steel	Steel		Above False Ceiling									Non-ACM				No	
DH109		Kitchen Staff Office	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small Fibrous & random	Ceiling									Non-ACM				No	Area Renovated
DH109		Kitchen Staff Office	Yes	Wall	Drywall	Drywall Joint Compound	Yellow	Walls						HM	1033216-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH109		Kitchen Staff Office	Yes	Structural	Firespray	Cementitious	Grey	Above False Ceiling						HM	32774-6-DH111-501abc	ND	Non-ACM		Misc. Blags		No	
DH109		Kitchen Staff Office	Yes	Floor	Pipe Insulation	Fiberglass Strapless and	White	Above False Ceiling									Non-ACM				No	
DH109		Kitchen Staff Office	Yes	Floor	Roll'd Vinyl Flooring	Vinyl	Dark/Brown with Red Fle	Floor									Non-ACM				No	
DH109		Kitchen Staff Office	Yes	Ducting	Steel	Steel		Above False Ceiling									Non-ACM				No	
DH110		Kitchen Staff Office	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small Fibrous & random	Ceiling									Non-ACM				No	Area Renovated
DH110		Kitchen Staff Office	Yes	Walls	Drywall	Drywall Joint Compound	Yellow	Walls						HM	1033216-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH110		Kitchen Staff Office	Yes	Structural	Firespray	Cementitious	Grey	Above False Ceiling						HM	1033216-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH110		Kitchen Staff Office	Yes	Piping	Pipe Insulation	Fiberglass Strapless and	White	Above False Ceiling									Non-ACM				No	
DH110		Kitchen Staff Office	Yes	Floor	Roll'd Vinyl Flooring	Vinyl	Dark/Brown with Red Fle	Floor									Non-ACM				No	Area Renovated
DH110		Kitchen Staff Office	Yes	Ducting	Steel	Steel		Above False Ceiling									Non-ACM				No	
DH111		Kitchen/Service	Yes	Walls	Ceiling Tile 2x4	Ceiling Tile	Small Fibrous & random	Ceiling									Non-ACM				No	Area Renovated
DH111		Kitchen/Service	Yes	Walls	Drywall	Drywall Joint Compound	Varies	Walls						HM	1033216-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH111		Kitchen/Service	Yes	Ceiling	Drywall	Drywall Joint Compound	Yellow	Ceiling									Non-ACM				No	
DH111		Kitchen/Service	Yes	Ducting	Ducting Insulation	Fiberglass	Foil Wrapped white & Y	Above False Ceiling									Non-ACM				No	
DH111		Kitchen/Service	Yes	Structural	Firespray	Cementitious	Grey	Above False Ceiling						SL	32774-6-DH111-501abc	ND	Non-ACM		Misc. Blags		No	
DH111		Kitchen/Service	Yes	Piping	Pipe Insulation	Fiberglass Strapless and	White	Above False Ceiling									Non-ACM				No	
DH111		Kitchen/Service	Yes	Wall	Roll'd Vinyl Flooring	Vinyl	Brown & Beige Marble	Floor									Non-ACM				No	
DH111A		Kitchen/Service	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small Fibrous & random	Ceiling									Non-ACM				No	Area Renovated
DH111A		Kitchen/Service	Yes	Walls	Drywall	Drywall Joint Compound	Varies	Walls						HM	1032116-502abc, 32774-DH&PM-502abcde 501ab		Non-ACM				No	
DH111A		Kitchen/Service	Yes	Ducting	Ducting Insulation	Fiberglass	Foil Wrapped white & Y	Above False Ceiling									Non-ACM				No	
DH111A		Kitchen/Service	Yes	Ducting	Ducting Insulation	Fiberglass	Foil Wrapped white & Y	Above False Ceiling									Non-ACM				No	
DH111A		Kitchen/Service	Yes	Structural	Firespray	Cementitious	Grey	Above False Ceiling						HM	0H 0H1-03-F5-54-001,0,N	ND	Non-ACM		07-225L		No	
DH111A		Kitchen/Service	Yes	Piping	Pipe Insulation	Fiberglass Strapless and	White	Above False Ceiling									Non-ACM				No	
DH111A		Kitchen/Service	Yes	Floor	Roll'd Vinyl Flooring	Vinyl	Brown & Beige Marble	Floor									Non-ACM				No	
DH112		Garbage Room	Yes	Floor	Concrete	Concrete	Grey	Floor									Non-ACM				No	
DH112		Garbage Room	Yes	Wall	Concrete Block Painted	Concrete	Beige															

Room No.	Room Name	Access	Inspected Item	Inspected Material	Material Composition	Material Description	Material Detailed Location	Friability	Approximate Quantity	PH(10)	Condition	Photograph	Sample / Identification Summary	Sample Name	% Asbestos & Fibre Type	Substrate Classification	Laboratory Report	Recommended Action	Recommended Abatement Operation	Asbestos Audit Documentation	General Notes
1	DH1-15 Eating Area	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-15 Eating Area	Yes	Walls	Drywall	Drywall Joint Compound	White	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-15 Eating Area	Yes	Ceiling	Drywall	Drywall Joint Compound	White	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-15 Eating Area	Yes	Structural	Concrete	Concrete	Grey	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	07-225L	-	-	No	Area Renovated
1	DH1-15 Eating Area	Yes	Floor	Floor Tile 12"x12"	Vinyl	Beige with with and bow	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-15 Eating Area	Yes	Piping	Pipe Insulation	Fiberglass Straights and	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Some areas of sealing not accurate assume asbestos may be present
1	DH1-15 Eating Area	Yes	Floor	Roller Vinyl Flooring	Vinyl	Brown Marble Finish	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-15 Eating Area	Yes	Ducting	Steel	Steel	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-15 Eating Area	Yes	Ceiling	Stucco	Stucco Finish	Yellow	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-16 Foyer	Yes	Ceiling	Drywall	Drywall Joint Compound	Yellow	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-16 Foyer	Yes	Walls	Drywall	Drywall Joint Compound	Brown	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Sampled during 2010 for 2011 Update. Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-16 Foyer	Yes	Ducting	Steel	Steel	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Conditions above ceiling unknown due to limited access
1	DH1-16 Foyer	Yes	Floor	Floor Tile 12"x12"	Vinyl	Beige with with and bow	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-16 Foyer	Yes	Piping	Pipe Insulation	Fiberglass Straights unk	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Conditions above ceiling unknown due to limited access
1	DH1-16 Foyer	Yes	Structural	Steel Deck on D.W.S.J.	Steel	Steel	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Conditions above ceiling unknown due to limited access
1	DH1-20 Office	Yes	Ducting	Steel	Steel	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Conditions above ceiling unknown due to limited access
1	DH1-20 Office	Yes	Plumbing	Carpot	Carpot	Purple	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Conditions above ceiling unknown due to limited access
1	DH1-20 Office	Yes	Floor	Carpot	Carpot	Purple	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Conditions above ceiling unknown due to limited access
1	DH1-20 Office	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-20 Office	Yes	Structural	Concrete and Steel	Concrete and Steel	Concrete and Steel	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-20 Office	Yes	Walls	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-22 Washroom Foyer	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-22 Washroom Foyer	Yes	Wall	Concrete Block Painted	Concrete	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-22 Washroom Foyer	Yes	Ceiling Upper	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-22 Washroom Foyer	Yes	Wall	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-22 Washroom Foyer	Yes	Ducting	Steel	Steel	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Sampled during 2010 for 2011 Update
1	DH1-22 Washroom Foyer	Yes	Piping	Pipe Insulation	Fiberglass Straights and	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-22 Washroom Foyer	Yes	Floor	Roller Vinyl Flooring	Vinyl	Brown Marble Finish	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	No	Area Renovated
1	DH1-23 Mens Washroom	Yes	Structural	Steel Deck on D.W.S.J.	Steel	Steel	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Wall	Concrete Block Painted	Concrete	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Wall	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Wall	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Ceiling	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Ceiling Upper	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Ducting	Steel	Steel	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Piping	Pipe Insulation	Fiberglass Straights and	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Floor	Roller Vinyl Flooring	Vinyl	Brown Marble Finish	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-23 Mens Washroom	Yes	Structural	Steel Deck on D.W.S.J.	Steel	Steel	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-24 Womens Washroom	No	Wall	Concrete Block Painted	Concrete	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-24 Womens Washroom	No	Wall	Drywall	Drywall Joint Compound	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-24 Womens Washroom	No	Ceiling	Drywall	Drywall Joint Compound	Yellow	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-24 Womens Washroom	No	Ducting	Steel	Steel	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-24 Womens Washroom	No	Piping	Pipe Insulation	Fiberglass Straights and	White	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-24 Womens Washroom	No	Ceiling Upper	Plaster	Plaster	Yellow	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-24 Womens Washroom	No	Floor	Roller Vinyl Flooring	Vinyl	Brown Marble Finish	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-24 Womens Washroom	No	Structural	Steel Deck on D.W.S.J.	Steel	Steel	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Assumed Room Finishes and Conditions same as Mens Washroom
1	DH1-17 Eating Area/Solarium	Yes	Walls	Brick	Brick	Red	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-17 Eating Area/Solarium	Yes	Floor	Floor Tile 12"x12"	Vinyl	Beige with with and bow	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-17 Eating Area/Solarium	Yes	Walls	Glass	Window Wall	Glass & Aluminum	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-17 Eating Area/Solarium	Yes	Ceiling	Glass	Window Wall	Glass & Aluminum	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-18 Vestibule	Yes	Walls	Brick	Brick	Red	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-18 Vestibule	Yes	Walls	Glass	Window Wall	Glass & Aluminum	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-18 Vestibule	Yes	Floor	Resin on Concrete	Vinyl/Rubber	Blue	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-18 Vestibule	Yes	Ceiling	Steel Painted	Steel	White	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57A Stairwell	Yes	Walls	Wood Painted	Wood Painted	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57A Stairwell	Yes	Ceiling	Plaster Painted	Plaster	Yellow	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57A Stairwell	Yes	Floor	Concrete	Concrete	Grey & White	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57B Stairwell	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Short Random Fissure	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57B Stairwell	Yes	Floor	Concrete	Concrete	Grey	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57B Stairwell	Yes	Wall	Concrete Block Painted	Concrete	Yellow-Blue	Wall	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57B Stairwell	Yes	Wall	Drywall	Drywall Joint Compound	White	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57C Stairwell	Yes	Structural	Reinforced Concrete	Concrete	Yellow	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57C Stairwell	Yes	Wall	Concrete Block Painted	Concrete	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57C Stairwell	Yes	Floor	Roller Vinyl Flooring	Vinyl	Brown Marble Finish	Floor	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
1	DH1-57C Stairwell	Yes	Ceiling	Steel Painted	Steel	Yellow	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
2	DH2-01 & D Stairwell Foyer	Yes	Walls	Brick	Brick	Red	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
2	DH2-01 & D Stairwell Foyer	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
2	DH2-01 & D Stairwell Foyer	Yes	Walls	Drywall Joint Compound	Drywall Joint Compound	White	Walls	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated
2	DH2-01 & D Stairwell Foyer	Yes	Ducting	Fiberglass	Fiberglass	White & Blue	Above False Ceiling	-	-	-	-	-	-	-	-	Non-ACM	-	-	-	-	Area Renovated

Room No.	Wing	Room Name	Access	Inspected Item	Inspected Material	Material Composition	Material Description	Material Detailed Location	Friability	Approximate Quantity	PH(10)	Condition	Photograph	Sample / Identification Summary	Sample Name	% Asbestos & Fibre Type	Substrate Classification	Laboratory Report	Recommended Action	Recommended Abatement Operation	Asbestos Abatement Documentation	General Notes
2		DH2-01 & D Stairwell Foyer	Yes	Pipe	Pipe Insulation	Fibreglass Straight and	White	Above False Ceiling	-								Non-ACM					
2		DH2-01 & D Stairwell Foyer	Yes	Insulation	Insulation	Polyurethane Foam Insul	Orange	Above False Ceiling	-								Non-ACM					
2		DH2-01 & D Stairwell Foyer	Yes	Floor	Terrazzo	Terrazzo	Brown & White	Floor	-								Non-ACM					
2		DH2-01 & D Stairwell Foyer	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					
2		DH2-01 & D Stairwell Foyer	Yes	Walls	Wood Painted	Wood Painted	Yellow & Green	Walls	-								Non-ACM					
2		DH2-02 Washroom Corridor	Yes	Walls	Drywall	Drywall Joint Compound	Brown	Walls	Non-Friable	700	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-02 Washroom Corridor	Yes	Ceiling	Drywall	Drywall Joint Compound	White	Ceiling	Non-Friable	25	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-02 Washroom Corridor	Yes	Ducting	Ducting Insulation	Fiberglass	Fall Wrapped white & V	Above False Ceiling	-								Non-ACM					
2		DH2-02 Washroom Corridor	Yes	Floor	Floor Tile 12" x 12"	Vinyl	White with brown flecks	Floor	-								Non-ACM					
2		DH2-02 Washroom Corridor	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					Area Renovated
2		DH2-03 Mens Washroom	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Short Random Fissures	Ceiling	-								Non-ACM					Area Renovated
2		DH2-03 Mens Washroom	Yes	Walls	Ceramic Glazed Brick	Concrete	Brown	Walls	-								Non-ACM					
2		DH2-03 Mens Washroom	Yes	Walls	Drywall	Drywall Joint Compound	Brown	Walls	Non-Friable	50	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-03 Mens Washroom	Yes	Ducting	Ducting Insulation	Fiberglass	Fall Wrapped white & V	Above False Ceiling	-								Non-ACM					Limited Ceiling Access
2		DH2-03 Mens Washroom	Yes	Walls	Plaster	Plaster	Brown	Walls	-				HM		32774-DH&PMS01abc_034127 501abc		Non-ACM		AMP			
2		DH2-03 Mens Washroom	Yes	Ceiling Upper	Plaster	Plaster	Brown	Above False Ceiling	-				HM		32774-DH&PMS01abc_034127 501abc		Non-ACM		AMP			
2		DH2-03 Mens Washroom	Yes	Floor	Terrazzo	Terrazzo	Brown & White	Floor	-								Non-ACM					
2		DH2-03 Mens Washroom	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					Limited Ceiling Access
2		DH2-04 Janitorial	Yes	Ducting	Ducting Insulation	Fiberglass	Fall Wrapped white & V	Above False Ceiling	-								Non-ACM					
2		DH2-04 Janitorial	Yes	Floor	Floor Tile 9" x 4"	Floor Tile	Green with white flecks	Floor	-								Non-ACM					Area Renovated
2		DH2-04 Janitorial	Yes	Ceiling	Plaster	Plaster	Gray	Ceiling	-				HM		32774-DH&PMS01abc_034127 501abc		Non-ACM		AMP			
2		DH2-04 Janitorial	Yes	Walls	Plaster	Plaster	Gray	Walls	-				SL		32774-DH&PMS01abc_ND		Non-ACM		Sampled during 2010 by AMP			Sampled during 2010 for 2013 Update
2		DH2-04 Janitorial	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					
2		DH2-05 Womens Washroom	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Short Random Fissures	Ceiling	-								Non-ACM					Area Renovated
2		DH2-05 Womens Washroom	Yes	Walls	Ceramic Glazed Brick	Concrete	Brown	Walls	-								Non-ACM					Area Renovated
2		DH2-05 Womens Washroom	Yes	Walls	Drywall	Drywall Joint Compound	Brown	Walls	Non-Friable	50	6.5 feet	Good					Suspect ACM		AMP			No access assume same as Men's Washroom
2		DH2-05 Womens Washroom	Yes	Ducting	Ducting Insulation	Fiberglass	Fall Wrapped white & V	Above False Ceiling	-								Non-ACM					Limited Ceiling Access
2		DH2-05 Womens Washroom	Yes	Walls	Plaster	Plaster	Brown	Walls	-				HM		32774-DH&PMS01abc_034127 501abc		Non-ACM		AMP			No access assume same as Men's Washroom
2		DH2-05 Womens Washroom	Yes	Ceiling Upper	Plaster	Plaster	Brown	Above False Ceiling	-				HM		32774-DH&PMS01abc_034127 501abc		Non-ACM		AMP			
2		DH2-05 Womens Washroom	Yes	Floor	Terrazzo	Terrazzo	Brown & White	Floor	-								Non-ACM					No access assume same as Men's Washroom
2		DH2-05 Womens Washroom	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					Limited Ceiling Access
2		DH2-05 Womens Washroom	Yes	Walls	Plaster	Plaster	Brown	Walls	-				HM		32774-DH&PMS01abc_034127 501abc		Non-ACM		AMP			No access assume same as Men's Washroom
2		DH2-05 Womens Washroom	Yes	Ceiling	Plaster	Plaster	Brown	Above False Ceiling	-				HM		32774-DH&PMS01abc_034127 501abc		Non-ACM		AMP			
2		DH2-06 Corridor	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					No access assume same as Men's Washroom
2		DH2-06 Corridor	Yes	Walls	Drywall	Drywall Joint Compound	Tan	Walls	Non-Friable	1000	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-06 Corridor	Yes	Ceiling	Drywall	Drywall Joint Compound	White	Ceiling	Non-Friable	600	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-06 Corridor	Yes	Ducting	Ducting Insulation	Fiberglass	In Vertical Chase Near Washrooms		-								Non-ACM					Conditions Above ceiling Unknown due to limited access
2		DH2-06 Corridor	Yes	Ducting	Ducting Insulation	Fiberglass		Above False Ceiling	-								Non-ACM					Conditions Above ceiling Unknown due to limited access
2		DH2-06 Corridor	Yes	Structural	Steel Deck on D.W.S.J.	Steel		Above False Ceiling	-								Non-ACM					Conditions Above ceiling Unknown due to limited access
2		DH2-06A Coat Closet	Yes	Structural	Carpet	Carpet Carpet over Coat	Purple Grey	Floor	-								Non-ACM					
2		DH2-06A Coat Closet	Yes	Walls	Drywall	Drywall Joint Compound	Tan	Walls	Non-Friable	200	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-06A Coat Closet	Yes	Ceiling	Drywall	Drywall Joint Compound	White	Ceiling	Non-Friable	25	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-06A Coat Closet	Yes	Ducting	Ducting Insulation	Fiberglass		Above False Ceiling	-								Non-ACM					Conditions Above ceiling Unknown due to limited access
2		DH2-06A Coat Closet	Yes	Structural	Steel Deck on D.W.S.J.	Steel		Above False Ceiling	-								Non-ACM					Conditions Above ceiling Unknown due to limited access
2		DH2-06B Coat Closet	Yes	Floor	Carpet	Carpet Carpet over Coat	Purple Grey	Floor	-								Non-ACM					
2		DH2-06B Coat Closet	Yes	Walls	Drywall	Drywall Joint Compound	Tan	Walls	Non-Friable	200	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-06B Coat Closet	Yes	Ceiling	Drywall	Drywall Joint Compound	White	Ceiling	Non-Friable	25	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-06B Coat Closet	Yes	Ducting	Ducting Insulation	Fiberglass		Above False Ceiling	-								Non-ACM					Conditions Above ceiling Unknown due to limited access
2		DH2-06B Coat Closet	Yes	Structural	Steel Deck on D.W.S.J.	Steel		Above False Ceiling	-								Non-ACM					Conditions Above ceiling Unknown due to limited access
2		DH2-07 Janitorial	Yes	Floor	Carpet	Carpet Carpet over Coat	Purple Grey	Floor	-								Non-ACM					
2		DH2-07 Janitorial	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-								Non-ACM					Area Renovated
2		DH2-07 Janitorial	Yes	Walls	Drywall	Drywall Joint Compound	Tan	Walls	Non-Friable	50	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-07 Janitorial	Yes	Ceiling	Drywall	Drywall Joint Compound	Tan	Ceiling	Non-Friable	50	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-07 Janitorial	Yes	Ducting	Ducting Insulation	Fiberglass	Fall Wrapped white & V	Above False Ceiling	-								Non-ACM					
2		DH2-07 Janitorial	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					
2		DH2-08 Meeting Room	Yes	Floor	Carpet	Carpet Carpet over Coat	Purple Grey	Floor	-								Non-ACM					
2		DH2-08 Meeting Room	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-								Non-ACM					Area Renovated
2		DH2-08 Meeting Room	Yes	Walls	Drywall	Drywall Joint Compound	Green	Walls	Non-Friable	1000	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-08 Meeting Room	Yes	Structural	Steel Deck on D.W.S.J.	Steel		Above False Ceiling	-								Non-ACM					
2		DH2-08 Meeting Room	Yes	Ducting	Ducting Insulation	Fiberglass		Above False Ceiling	-								Non-ACM					
2		DH2-10 Kitchen	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-								Non-ACM					Area Renovated
2		DH2-10 Kitchen	Yes	Walls	Drywall	Drywall Joint Compound	Tan	Walls	Non-Friable	4000	6.5 feet	Fair					Suspect ACM		AMP			
2		DH2-10 Kitchen	Yes	Structural	Steel Deck on D.W.S.J.	Steel		Above False Ceiling	-								Non-ACM					
2		DH2-10 Kitchen	Yes	Ducting	Ducting Insulation	Fiberglass	Silver	Above False Ceiling	-								Non-ACM					
2		DH2-10 Kitchen	Yes	Floor	Floor Tile 12" x 12"	Vinyl	White with brown flecks	Floor	-								Non-ACM					Area Renovated
2		DH2-11 Paul Martin Centre	Yes	Floor	Carpet	Carpet Carpet over Coat	Purple Grey	Floor	-								Non-ACM					
2		DH2-11 Paul Martin Centre	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-								Non-ACM					Area Renovated
2		DH2-11 Paul Martin Centre	Yes	Walls	Drywall	Drywall Joint Compound	Tan	Walls	Non-Friable	2000	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-11 Paul Martin Centre	Yes	Ceiling	Drywall	Drywall Joint Compound	Tan	Ceiling	Non-Friable	300	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-11 Paul Martin Centre	Yes	Ducting	Ducting Insulation	Fiberglass	Fall Wrapped white & V	Above False Ceiling	-								Non-ACM					
2		DH2-11 Paul Martin Centre	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					
2		DH2-11A Audio Visual Storage	Yes	Floor	Carpet	Carpet Carpet over Coat	Purple Grey	Floor	-								Non-ACM					
2		DH2-11A Audio Visual Storage	Yes	Ceiling	Ceiling Tile 2x4	Ceiling Tile	Small fissure & random	Ceiling	-								Non-ACM					Area Renovated
2		DH2-11A Audio Visual Storage	Yes	Walls	Drywall	Drywall Joint Compound	Tan	Walls	Non-Friable	50	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-11A Audio Visual Storage	Yes	Ceiling	Drywall	Drywall Joint Compound	Tan	Ceiling	Non-Friable	50	6.5 feet	Good					Suspect ACM		AMP			
2		DH2-11A Audio Visual Storage	Yes	Ducting	Ducting Insulation	Fiberglass	Fall Wrapped white & V	Above False Ceiling	-								Non-ACM					
2		DH2-11A Audio Visual Storage	Yes	Structural	Wood Deck on Steel Be	Wood & Steel	-	Above False Ceiling	-								Non-ACM					
2		DH2-12 Foyer	Yes	Floor	Carpet	Carpet Carpet over Coat	Purple Grey	Floor	-								Non-ACM					New Construction
2		DH2-12 Foyer	Yes	Walls	Drywall	Drywall Joint Compound	Green	Walls	-								Non-ACM					New Construction
2		DH2-12 Foyer	Yes	Ceiling	Drywall	Drywall Joint Compound	Green	Ceiling	-								Non-ACM					New Construction
2		DH2-12 Foyer	Yes	Ducting	Ducting Insulation	Fiberglass		Above False Ceiling	-								Non-ACM					New Construction



Room	Wing	Room No.	Room Name	Access	Inspected Item	Inspected Material	Material Composition	Material Description	Material Detailed Location	Friability	Approximate Quantity	PHOTO	Condition	Photograph	Sample / Identification Summary	Sample Name	% Asbestos & Fibre Type	Substrate Identification	Laboratory Report	Recommended Action	Recommended Abatement Operation	Asbestos Abatement Documentation	General Notes															
<b>Additional ACM Bulk Sampling Log (Annual Re-Assessment Updates)</b>																1033216-503abc; 32774-DH&PM-502abcde-503a	Non-ACM																					
1		DH101	Storage	Yes	Structural	Firestray	Cementitious	Gray	Steel Deck & C.W.S.I.					SL	32774-120-501abc	ND	Non-ACM		See Abatement Report				32774-120															
1		DH1-11	Kitchen/Service	Yes	Structural	Firestray	Cementitious	Gray	Above False Ceiling					SL	32774-6-DH111-501abc	ND	Non-ACM		Misc. Blades				No															
1		DH103	Loadline Deck	Yes	Structural	Firestray	Cementitious	Gray	Steel Deck & C.W.S.I.					SL	On DH1-03-25-54-001.06	ND	Non-ACM		07-225SL				No															
1		DH1-24	Womens Washroom	No	Ceiling	Drywall	Drywall Joint Compound	Yellow	ceiling					SL	3033216-502abc	ND	Non-ACM			AMP			No	Sampled during 2010 for 2011 Update. Assumed Room Finishes and Conditions same as Mens Washroom														
1		DH1-16	Foyer	Yes	Walls	Drywall	Drywall Joint Compound	Brown	Walls					SL	32774-DH&PM-502abc	ND	Non-ACM			AMP		No	Sampled during 2010 for 2011 Update. Assumed Room Finishes and Conditions same as Mens Washroom															
1		DH1-22	Washroom Foyer	Yes	Wall	Drywall	Drywall Joint Compound	Yellow	Walls					SL	32774-DH&PM-502de	ND	Non-ACM		Sampled during 2010 for 2011 Update	AMP		No	Sampled during 2010 for 2011 Update															
1		DH107	Storage	Yes	Wall	Drywall	Drywall Joint Compound	Beige	Wall					SL	32774-DH&PM-503a	ND	Non-ACM		Sampled during 2010 for 2011 Update	AMP		No	Sampled during 2010 for 2011 Update. Assumed Room Finishes and Conditions same as Mens Washroom															
1		DH15B	Stairwell	Yes	Wall	Drywall	Drywall Joint Compound		Walls					SL	32774-DH&PM-503bc	ND	Non-ACM			AMP		No	Sampled during 2010 for 2011 Update. Assumed Room Finishes and Conditions same as Mens Washroom															
2		DH2-04	Janitorial	Yes	Walls	Plaster	Plaster	Gray	Walls					SL	32774-DH&PM501abc	ND	Non-ACM		Sampled during 2010 for 2011 Update	AMP		No	Sampled during 2010 for 2011 Update. Assumed Room Finishes and Conditions same as Mens Washroom															
1		DH1-24	Womens Washroom	No	Ceiling Upper	plaster	plaster	Yellow	ceiling					SL	1134127-501abc		Non-ACM			AMP			No	Sampled during 2010 for 2011 Update. Assumed Room Finishes and Conditions same as Mens Washroom														